



Prevent Falls

- Wear and use personal fall arrest equipment.
- Install and maintain perimeter protection.
- Cover and secure floor openings.
- Label floor opening covers.
- Use ladders and scaffolds safely.



Prevent Struck-by

- Ensure all vehicles have operable back-up alarms or use a spotter to direct movement.
- Check all vehicles at the beginning of each shift to ensure that all equipment and accessories are in safe operating condition.
- Wear high-visibility clothes near equipment/vehicles.
- Never position yourself between moving and stationary objects.



Prevent Electrocutations

- Locate and identify utilities before starting work.
- Look for overhead power lines when operating any equipment.



Prevent Caught-In/Between

- Never enter an unprotected trench or excavation 5 feet or deeper without an adequate protective system in place; some trenches fewer than 5 feet deep may also need such a system.
- Make sure the trench or excavation is protected by sloping, shoring, benching or trench shield systems.



Cherie Berry

Commissioner of Labor

Education, Training and Technical Assistance Bureau

919-807-2875 • 1-800-625-2267 • www.nclabor.com

Sign up to receive a free subscription to the *NC Labor Ledger* at

www.nclabor.com/news/ledger.htm

Printed 7/07

500 copies of this public document were printed at a cost of \$40, or \$.08 per copy.