



FALL PROTECTION



- Identify all potential tripping and fall hazards before work starts.
- Look for fall hazards such as unprotected floor openings/edges, shafts, skylights, stairwells and roof openings/edges.
- Inspect fall protection equipment for defects before use.
- Select, wear and use fall protection equipment appropriate for the task.
- Inspect, secure and stabilize all ladders before climbing them.



- Never stand on the top rung/step of a stepladder.
- Use handrails when you go up or down stairs.
- Practice good housekeeping. Keep cords, welding leads and air hoses out of walkways or adjacent work areas.

Adapted from OSHA Quick Card 3257-11R-05, U.S. Department of Labor.



NCDOL
N.C. Department of Labor

Cherie Berry, Commissioner of Labor

Education, Training and Technical Assistance Bureau
919-807-2875 • 1-800-625-2267 • www.nclabor.com

Sign up to receive a free subscription to the *NC Labor Ledger* at
www.nclabor.com/news/ledger.htm

Printed 2/12

500 copies of this public document were printed at a cost of \$40, or \$.08 per copy.